

## SUMMARY OF CHANGES

Addenda to the 2001 Edition of the Code are issued in the form of replacement pages. Revisions, additions, or deletions are incorporated directly into the affected pages. It is advisable, however, that all replaced pages be retained for reference.

Replace or insert the pages listed. Changes given below are identified on the pages by a margin note, **A02**, placed next to the affected area. Revisions to the 2001 Edition are indicated by **01**. For the listing below, the *Page* references the affected area. A margin note, **A02**, placed next to the heading indicates *Location*. Revisions are listed under *Change*.

<i>Location</i>	<i>Page</i>	<i>Change</i>
Listing of Sections	iii	Title to Section III, Division 2 revised
Roster	xiii–xxii	Updated to reflect A02
ASTM Roster	xxiii	Updated to reflect A02
Specification Listed by Materials	xxvii–xxxii	Updated to reflect A02
Specifications Listed in Numeric Sequence	xxxiii–xxxvii	Updated to reflect A02
Appendix 2	xli–xliv	(1) Under Application, second paragraph deleted (2) Under Mechanical Properties, first two paragraphs revised and next two added
Appendix A	xl–liv	Updated to reflect A02
SA-20/SA-20M	85–130	Revised in its entirety
SA-36/SA-36M	157–163	Revised in its entirety
SA-182/SA-182M	253–273.1	Revised in its entirety
SA-193/SA-193M	287	Table 2 corrected by Errata
SA-213/SA-213M	340–351	Revised in its entirety
SA-214/SA-214M	352	Subtitle revised
	353	Paragraph 7.2 revised
SA-231/SA-231M	371.1–371.5	Added
SA-240	387	Subtitle revised
	393	Table 2 revised
SA-250/SA-250M	406	Subtitle revised
	409.1	Supplementary Requirement added
SA-276	462.1–462.10	Added
SA-307	481–488	Revised in its entirety
SA-312/SA-312M	494–507	Revised in its entirety
SA-325	520–530	Revised in its entirety
SA-335/SA-335M	553–564	Revised in its entirety
SA-336/SA-336M	566, 566.1	Paragraph 6.2 revised
SA-354	606–615	Revised in its entirety
SA-358/SA-358M	620	Paragraph 14.3 corrected by Errata
SA-513	925.1–925.26	Added

<i>Location</i>	<i>Page</i>	<i>Change</i>
SA-574	1050–1058	Revised in its entirety
SA-737/SA-737M	1259	Table 1 corrected by Errata
SA-1016/SA-1016M	1460.1–1460.14	Added
SA/EN 10028-3	1474	Revised in its entirety

**NOTE:**

Volume 50 of the Interpretations to Section II, Part A, of the ASME Boiler and Pressure Vessel Code follows the last page of this.